



# Cost-saving ETR<sup>TM</sup> Overhaul Services LIEBHERR AEROSPACE MOTOR PART NUMBER: S4019

## AFFORDABLE ALTERNATIVE TO OEM NEW

LIEBHERR AEROSPACE MOTOR PART NUMBER: \$4019



Fitted to Liebherr Aerospace Cabin Pressure
Outflow Valve p/n 88005B Series (88005B203,
88005B204, 88005B205, 88005B206, 88005B304,
88005B305, and 88005B306) for the Airbus A300-600
and A310 Aircraft



#### **PROBLEM**

Premature and unscheduled removal of the outflow valve because the motor assembly failed. The motor failure was primarily caused by damaged windings, excessive bearing wear, overheating, or a combination of these factors.

# SOLUTION

Repair motor assembly with approved overhaul/repair specifications. Motor assemblies shall meet all repair, testing, and inspection criteria as outlined in NAASCO's FAA-DER approved overhaul/repair process.

# SUBSTANTIAL SAVINGS

An affordable alternative to OEM New replacements, the repaired motor assembly is restored and returned to service in 'like new' condition.

### COMMITMENT TO EXCELLENCE

Since 1984, we have provided cost-effective repair solutions for a variety of aircraft components. We strive to maintain the highest quality, reliability, and dependability levels to give you the "Best Value" for your maintenance dollar.

Contact us at <u>Sales@NAASCO.com</u> for more information about our cost-saving Liebherr Aerospace motor services.

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967 Tel: 631-399-2244 • www.NAASCO.com • Fax: 631-399-2275 FAA Repair Station No. FD1R135K / EASA.145.4687 / UK.145.50472