



Cost-saving Overhaul Services For EATON Speed Brake Actuator Motors

**AFFORDABLE
ALTERNATIVE TO OEM NEW**



Motor Part Number:
PN 684SC112-1
PN 684SC112-3

**FITTED TO BOEING
B757 ▪ B767 ▪ B777**

MOTOR APPLICATIONS INCLUDE:

EATON Speed Brake Actuator
(End Item Number)

684D100-1 ▪ 684D100-3 ▪ 684D100-5
684D100-7 ▪ 684D100-9 ▪ 684D100-11
684D100-13 ▪ 684D100-15 ▪ 684D100-17

NEW ITEM!

PROBLEM

Premature/Unscheduled removal of motor assembly from NHA. Motor failure caused by damaged windings, excessive bearing wear, overheating or a combination of these factors.

SOLUTION

Repair motor assembly with approved repair specification. Motor assemblies shall meet all repair, testing, and inspection criteria as outlined in NAASCO's FAA-DER approved repair process.

SUBSTANTIAL SAVINGS

An affordable alternative to OEM New replacements, the repaired motor assembly is restored and returned to service in 'like new' condition.

COMMITMENT TO EXCELLENCE

Since 1984, we have provided cost-effective repair solutions for a variety of aircraft components. We strive to maintain the highest levels of quality, reliability, and dependability to give you the "Best Value" for your maintenance dollar.

**Contact NAASCO today for more
information on our cost-saving
ETR™ Motor Repair Programs**