



Sil-Met™ REPAIR SOLUTIONS For Power Relays, Contacts, and Terminal Boards

ENJOY SUBSTANTIAL SAVINGS
OVER THE COST OF OEM NEW

POWER RELAY FITTED TO:
DC 9 ▪ MD 80



PN: 9008D09

REPAIRED TERMINAL BOARD



PN: 977J237

REPAIRED CONTACTS



PN: 965C861-1

FAA AND AIRLINE APPROVED REPAIR PROCESS FOR INDIVIDUAL CONTACTS AND RELAY ASSEMBLIES

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967
Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275
FAA Repair Station No. FD1R135K / EASA.145.4687