

Repairs for Honeywell Landing Light Assembly



Motor Assembly
46-2788-1
converted to
46-2788-3
at
NO EXTRA CHARGE

- TURN CONSUMABLE INTO REPAIRABLE
- FAA-DER APPROVED REPAIR PROCESS
- RAPID TURN TIMES AND SUBSTANTIAL SAVINGS
- ALL REPAIRED MOTORS
 SHIPPED WITH DUAL
 RELEASE 8130- 3 TAG

