

Sil-Met™ REPAIR SOLUTIONS for Hartman Power Relays.



A-700-Series



A-2042C PDU



A-2043C PDU



A-770



A-1077-Series



A-703-Series



AN-3025-1



B-102F

Partial list of Contact part numbers for relays shown above:



- 32054-010 (Post, Left Contact)
- 32055-010 (Post, Right Contact)
- 11631-090 (Contact, Movable)
- ...and much more



FAA AND AIRLINE APPROVED REPAIR PROCESS
REPAIR OF INDIVIDUAL CONTACTS OR RELAY SWITCHING ASSEMBLIES

- **Start your own exchange pool.**
- **Turn Consumable into Repairable**
- **Substantial Savings over the cost of OEM**

OEM Quality at a fraction of OEM Price



NAASCO Northeast Corp.

NAASCO NORTHEAST CORP., 222 GRAND AVENUE, BROOKHAVEN AIRPORT, SHIRLEY, NEW YORK 11967

Tel: 631-399-2244 • WWW.NAASCO.COM • Fax: 631-399-2275

FAA repair station No. FD1R135K /EASA.145.4687