


Sil-Met™ REPAIR SOLUTIONS for Hartman A-1077-Series Power Relays.

Sil-Met™ "Next Generation" repair solutions available for the following part numbers:

- A-1077 • A-1077B
- A-1077D • A-1077DD • A-1077F
- A-1077V • A-1077W



Hartman A-1077-Series fitted to
BOEING • BELL • SIKORSKY

NAASCO offers the industry's only FAA-approved repair process for A-1077-Series Relays

- *Start your own exchange pool.*
- *Turn Consumable into Repairable*
- *Substantial Savings over the cost of OEM*



OEM Quality at a fraction of OEM Price

NAASCO NORTHEAST CORP. 222 GRAND AVENUE, BROOKHAVEN AIRPORT, SHIRLEY, NEW YORK 11967

Tel: 631-399-2244 • WWW.NAASCO.COM • Fax: 631-399-2275

FAA repair station No. FD1R135K / EASA.145.4687