





## Bombardier DHC-8 Q400 Contactor Support

CUT COSTS WITHOUT COMPROMISING QUALITY



### Honeywell Contactor

PN: 1095998-1  
(ECE PN 815CA01)



### Honeywell Contactor

PN: 1096224-2  
(ECE PN 227CC02AY00)



**Substantial savings over OEM New**

### COST-EFFECTIVE

Increase your Return on Investment! Extend the life of your contactors – return them to 'like new' condition with our advanced Sil-Met™ Repair Solutions.

### NAASCO DELIVERS

Quality service. Rapid turn around times. Repaired contactors shipped with 8130-3/EASA Form 1 tags.

### COMMITMENT TO QUALITY

Since 1984, we have provided cost-effective repair solutions for a variety of aircraft components. We strive to maintain the highest levels of quality, reliability, and dependability to give you the "Best Value" for your maintenance dollar.

**Contact NAASCO today for more information on our cost-saving Sil-Met™ Repair Solutions.**

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967

Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275

FAA Repair Station No. FD1R135K / EASA.145.4687