



Sil-Met™ REPAIR SOLUTIONS for Airbus E.C.E. Relays

E.C.E. RELAY FITTED TO AIRBUS FAMILY



PN's include:

- 477CA01C15-02Y2
- 477CA01C15-02Y3

- TURN CONSUMABLE INTO REPAIRABLE
- COST-EFFECTIVE ALTERNATIVE TO OEM NEW
- RAPID TURN AROUND TIMES
- ISSUED WITH FAA/EASE DUAL RELEASE 8130-3 TAG

CUT COSTS WITHOUT COMPROMISING QUALITY!

REPAIRED TERMINAL BLOCK AND CONTACT ASSY

PN: CA4374SC2

Advanced Repair Technology
Cost-effective alternative to OEM New




REPAIRED TERMINAL BLOCK (DETACHED)



REPAIRED MOVING CONTACT ASSY

PN: CA4330



**FAA/DER APPROVED REPAIR PROCESS TURNS YOUR
CONSUMABLES INTO REPAIRABLE AT A FRACTION OF OEM NEW**

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967

Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275

FAA Repair Station No. FD1R135K / EASA.145.4687