



Affordable Repair Solutions for Honeywell ELCUs Fitted to Boeing B747 ▪ B757 ▪ B767

Sil-Met™ Repair Technology*
Cost-effective alternative
to OEM new



ELCU Support Include:

- | | |
|---------|---------|
| 3B39-1B | 3B41-1A |
| 3B39-1C | 3B41-1B |
| 3B39-2A | 3B41-3A |
| 3B50-2A | 3B41-3B |

*Limited to piece part support only

BUS BAR/CURRENT TRANSFORMER ASSEMBLIES

1593926-1



1593926-2



1593926-3

Coil Assy

1593917-1



Operator Assy

1593909-1



Bus Bar/Contact Assy

1593921-1



1593921-2



FAA APPROVED REPAIR PROCESS TURNS YOUR CONSUMABLE PIECE PARTS INTO REPAIRABLE

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967

Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275

FAA Repair Station No. FD1R135K / EASA.145.4687