




Affordable REPAIR SOLUTIONS For Micropump PN 83427 Lavatory Pump

OEM QUALITY AT A FRACTION OF OEM PRICE



Micropump

PN: 83427

(Canadair No.: 601R43135-3)



Motor Assembly

PN: 7134

Pump Model:

- 668-28
- 668-400-2
- 668D3
- 668D5
- 09-31-326

Model Part No.:

- 8940
- 8700
- 9168
- 9162
- 83427

Application:

- Pump, Water
- Pump, Coffee
- Pump, Coffee
- Pump, Coffee
- Pump, Coffee/Lavatory

- COST-EFFECTIVE REPAIRS
- TURN CONSUMABLE INTO REPAIRABLE
- SUBSTANTIAL SAVINGS OVER THE COST OF OEM

FAA/EASA APPROVED REPAIR PROCESS

REPAIR/OVERHAUL OF MOTOR ASSEMBLY OR COMPLETE PUMP ASSEMBLY

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967

Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275

FAA Repair Station No. FD1R135K / EASA.145.4687