



Affordable REPAIR SOLUTIONS For Champion Transformer Rectifier Units

OEM QUALITY AT A FRACTION OF OEM PRICE

Champion Aerospace Converter:

Champion Aerospace Blower:



PN: 28VS200Y-4DH TRU
Fitted to DHC-8-100 thru -300 Series



FAA-Approved Repair
Process for Fan Motor
PN: 2031526



PN: MS17976-2*
Fitted to CRJ and Challenger Aircraft



FAA-Approved Repair
Process for Fan Motor
PN: 2652652

*Also fitted to ERJ as PNs: 28VS100Y-10A, -10B, -10C

QUALITY SERVICE • RAPID TURN TIMES • COST-EFFECTIVE REPAIRS • SUBSTANTIAL SAVINGS

Overhauled units shipped with 8130-3/EASA Form 1 tags

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967
Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275
FAA Repair Station No. FD1R135K / EASA.145.4687