



Sil-Met™ REPAIR SOLUTIONS For Hamilton Sundstrand Power Relays

OEM QUALITY AT A FRACTION OF OEM PRICE

900D09-Series





942D023-Series



941D335-Series



914F567-Series



Sil-Met™ "Next Generation" Repair Solutions
available for the following PNs:

- 962C526-1
- 946B015-1
- 966C748-1
- 941D739-3
- 965C861-1
- 946B016-1
- 966C748-2
- 946F029-1
- 965C321-1
- 946B011-1
- 9D8554-2
- 946F429-13
- 965C321-3
- 947B179-1
- 14D3020-3
- 977J237-1
- 946B005-1
- 949B071-1
- 14D3021-3
- ...and much more

- START YOUR OWN EXCHANGE POOL
- TURN CONSUMABLE INTO REPAIRABLE
- SUBSTANTIAL SAVINGS OVER THE COST OF OEM

FAA AND AIRLINE APPROVED REPAIR PROCESS FOR INDIVIDUAL CONTACTS, TERMINAL BOARDS, OR POWER RELAYS

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967
Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275
FAA Repair Station No. FD1R135K / EASA.145.4687