



Cost-Saving ETR™ Motor Repair Technology OEM Quality at a Fraction of OEM Price



PN: 46-2788-1*

*Converted to 46-2788-3 at
NO EXTRA CHARGE

HONEYWELL

Landing Light Motor Support
For Boeing B737 NG-Family


Overhauled units
shipped with
8130-3/EASA
Form 1 tags

Fitted to Honeywell Landing Light
NHA: 45-0351



PN: 46-2788-3

Landing Light Motor Support
For Boeing MD-88 ▪ MD-90



PN: 20135-2

Fitted to Honeywell Landing Light NHA: 45-0057

Windshield Wiper Motor Support
For Boeing B757 ▪ B767-200, -300



PN: 55-1548-1

Windshield Wiper NHA: PN 90-0215-1 thru -4

Windshield Wiper Motor Support
For Boeing B767-666



PN: 55-1488-1

Windshield Wiper NHA: PN 90-0205-1

Windshield Wiper Motor Support
For Boeing B767-300 ▪ B767-400ER ▪ B777-200



PN: 55-2220-1

Windshield Wiper NHA: PN 90-0408-7 thru -12

UNCOMPROMISED QUALITY ▪ FAA / E.A.S.A APPROVED ▪ EXCEPTIONAL VALUE

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967

Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275

FAA Repair Station No. FD1R135K / EASA.145.4687

ADVANCED ETR™ MOTOR TECHNOLOGY
The affordable alternative to OEM New!



ROSEMOUNT®

Windshield Wiper Motor Support
For Boeing 737-NG

PN: 02311-0290-0002




Fitted to Wiper Motor Converter
Assembly PNs: ▪ 2313M-347-4(LH)
▪ 2313M-348-4 (RH)

EATON

Speed Brake Actuator Motor
For Boeing B757 ▪ B767 ▪ B777

PNs:

- 684SC112-1
- 684SC112-3



Fitted to Speed Brake Actuator NHA:
684D100-1, -3, -5, -7, -9, -11, -13, -15, -17

ECE - Teleflex

Landing Light Motor
For Airbus A300-Series

PNs:


- 4195798
- 4387329



Fitted to Landing Light NHA:
PNs 4191695 ▪ 4331772 ▪ 4315542

Teleflex - Syneravia

Windshield Wiper Motor for ATR 42/72



PN: 3112223

Fitted to Motor-Converter Gear Case NHA:
4216016 (LH) ▪ 4216009 (RH)



Fan Motor Support for
Champion TRUs/ Converters



PN: 2031526

Fitted to Converter/TRU NHA:
PN 28VS200Y-4DH (for
Bombardier DHC-8-100, -200, -300)



PN: 2652652

Fitted to NHA: PN 28VS100Y-
10A, -10BPN, -10C
(for ERJ/CRJ/Challenger)

MICROPUMP®

Micropump Motor
For CRJ/Challenger

PN: 7134



Fitted to Water/Lav Pump NHA: PN 83427



Mach Trim Actuator Support
For Boeing B737-Series

MPC Products Stator & Housing Assy
Fitted to Motor Brake Assy PN 1461200101A
Used on Mach Trim Actuator PN 2A7200A
(Boeing PN 10-61368-7)



PN: 1963405802A



Airbus | A300 Series | ECE/Teleflex

Landing Light Motor # 4387329 ▪ 4195798
Landing Light Model # 4191695 ▪ 4331772 ▪ 4315542

ATR | 42 & 72 | Teleflex/Syneravia

Windshield Wiper Motor # 3112223
Windshield Wiper Converter # 4126016 ▪ 4126009

Boeing | B737 | MPC Products

Mach Trim Actuator Stator & Housing # 1963405802A
Mach Trim Actuator # 2A7200A

Boeing | B737NG | Honeywell/Grimes

Landing Light Motor # 46-2788-1 ▪ 46-2788-3
Landing Light Model # 45-0351

Boeing | B737NG | Rosemount

Windshield Wiper Motor # 02311-0290-0002
Windshield Wiper Converter # 2313M347-3 /4 ▪ 2313M348-3 /4

Boeing | B757 & B767 | Honeywell/Grimes

Windshield Wiper Motor # 55-1548-1 ▪ 55-1488-1
Windshield Wiper Assy # 90-0215-1 ▪ 90-0205-1

Boeing | B757, B767, B777 | Eaton

Speed Brake Actuator Motor # 684SC112-1 ▪ 684SC112-3
Actuator # 684D100 Series

Boeing | B777 | Honeywell

Windshield Wiper Motor # 55-2220-1
Windshield Wiper Assy # 90-0408-7 thru 12

Boeing | MD88 & MD90 | Honeywell/Grimes

Landing Light Motor # 20134-2
Landing Light Model # 45-0057 ▪ 45-0057-3

Bombardier | CRJ-100, -200, -300, Challenger | Champion

Cooling Fan Motor # 2652652
Static Converter # MS17976-2/28VS100Y-10A, 10B, 10C

Bombardier | CRJ-100, -200, -300, Challenger | Champion

Micropump Motor # 7134
Water Pump # 83427

Bombardier | Dash 8-100, -200, -300 | Champion

Cooling Fan Motor # 2031526
Static Converter # 28VS200Y-4DH

FAA/EASA Approved
ETR™ Electrical
Motor Repairs