

Motor Repairs for Rosemount Wiper Motor Converter

WIPER MOTOR CONVERTER 2313M-347-4 (LEFT HAND) 2313M-348-4 (RIGHT HAND) Cost-Saving ETR Motor Repair Technology OEM Quality at a Fraction of OEM Price

OVERHAULED / REPAIRED MOTOR ASSEMBLY PN: 02311-0290-0002

- TURN CONSUMABLE MOTORS INTO REPAIRABLE
- FAA-DER APPROVED .REPAIR PROCESS
- SUBSTANTIAL SAVINGS
 - ALL REPAIRED MOTORS SHIPPED WITH DUAL RELEASE 8130-3 TAG

MOTOR MFR: ROSEMOUNT P/N: 02311-029-000 ES/N: 07591 Overhauled by NARSV 631-399-224

NAASCO, 222 Grand Ave. Brookhaven Airport, Shirley, NY 11967 Tel: 631-399-2244 • www.naasco.com • Fax: 631-399-2275 FAA Repair Station No. FD1R135K / EASA.145.4687